



Front View

Rear View




Loose/broken/delaminated  
Damage/wear/hole

Previous repair  
Replaced piece

Missing  
Spindles not original to desk

Add-ons  
Inscriptions


Right Side



■ Loose/broken/delaminated  
■ Damage/wear/hole

■ Previous repair  
■ Replaced piece

Left Side




■ Missing  
■ Spindles not original to desk

■ Add-ons  
■ Inscriptions

*Note: No cross-banding*

Top



Note: no opening for inkwell


Loose/broken/delaminated  
Damage/wear/hole

Previous repair  
Replaced piece

Missing  
Spindles not original to desk

Add-ons  
Inscriptions


Bottom



Loose/broken/delaminated  
Damage/wear/hole

Previous repair  
Replaced piece

Bottom




Missing  
Spindles not original to desk



Add-ons  
Inscriptions



Drawer Front, Outer Surface







Rear Surface of Drawer Front



 Loose/broken/delaminated  
 Damage/wear/hole



 Previous repair  
 Replaced piece



 Missing  
 Spindles not original to desk



 Add-ons  
 Inscriptions



Inside Surface of Left Drawer Side



Inside Surface of Right Drawer Side




 Loose/broken/delaminated  
 Damage/wear/hole

 Previous repair  
 Replaced piece


 Missing  
 Spindles not original to desk

 Add-ons  
 Inscriptions

Rear Surface of Drawer Back



Front Surface of Drawer Back



■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece

■ Missing



■ Spindles not original to desk

■ Add-ons




■ Inscriptions



Upper Surface of Drawer Bottom

 Loose/broken/delaminated Damage/wear/hole Previous repair Replaced piece


Lower Surface of Drawer Bottom



 Missing Spindles not original to desk Add-ons Inscriptions







Outside Surface, Right Drawer Side



Outside Surface, Left Drawer Side



 Loose/broken/delaminated  
 Damage/wear/hole

 Previous repair  
 Replaced piece

 Missing  
 Spindles not original to desk

 Add-ons  
 Inscriptions